| Total No. of Questions | : | 6] |
|-------------------------------|---|------------|
| P484 | | |

| SEAT No.: | | | |
|-----------|----|----------|-----|
| [Total | No | of Dogos | . າ |

TE/Insem/APR - 10 T.E. (Mechanical) MANUFACTURING PROCESS - II (2012 Pattern) (Semester - II)

| (2012 Pattern) (Semester - 11) | | | | |
|--------------------------------|--------|--|--|--|
| Time | :1E | Hour] [Max. Marks : 30 | | |
| Instri | uction | ns to the candidates : | | |
| | 1) | Answer Q1 or Q2, Q3 or Q4, Q5 or Q6. | | |
| | 2) | Figures to the right indicate full marks. | | |
| | 3) | Use of electronic pocket calculator is allowed. | | |
| | 4) | Assume suitable data if necessary. | | |
| Q 1) | a) | Explain the following with neat sketch. [6] | | |
| | | i) Spot facing | | |
| | | ii) Counter sinking | | |
| | | iii) Trepanning | | |
| | b) | Explain Thread milling with neat sketch. [4] | | |
| | | OR | | |
| Q2) | a) | Draw and explain Broach tool geometry. [6] | | |
| | b) | Calculate the Index Crank movement for 69 divisions by compound indexing methods. [4] Plate No. 01:-15, 16, 17, 18, 19, 20 Plate No. 02:-21, 23, 27, 29, 31, 33 Plate No. 03:-37, 39, 41, 43, 47, 49 | | |
| Q3) | a) | Explain mounting of grinding wheels with neat sketch. [6] | | |
| | b) | Write a short note on buffing. [4] | | |

P.T.O.

a) Explain in brief lapping process. Also list out Advantages and Limitations. *Q4*) [6] b) What do you mean by Loading and Glazing of grinding wheel? [4] *Q5*) Derive an expression for shear angle with chip thickness ratio. [6] b) A seamless tube of 50 mm outside diameter is turned on lathe with cutting speed of 20 m/min. The tool rake angle is 15° and feed rate is 0.2 mm/rev. The length of chip in one revolution measures 80 mm. Calculate Chip thickness ratio i) Shear Plane angle ii) Shear flow speed iii) Shear strain iv) OR The following equation for tool life is given for turning operation, **Q6)** a) $VT^{0.13}f^{0.77}d^{0.37} = C$. A 70 minute tool life was obtained while cutting at V = 35 m/min, f = 0.3 mm/rev and d = 2 mm. Determine the change in tool life if the cutting speed, feed and depth of cut are increased by 20% individually and also taken together. .ditions b) What is built up edge and how is it formed? What are the conditions that lead to formation of built up edge?